ABSTRACT

[0041] A method of increasing the collapse resistance of a tubular comprises locating a tool having at least one, and typically three, bearing members within a tubular. The bearing members are positioned in engagement with a wall of the tubular to apply a radial force to a discrete zone of the wall. This radial force is then applied to further discrete zones of the wall, the level of radial force being selected such that the collapse resistance of the tubular is increased.